



Image 1 - Back yard view of 16 Monaco Dr.



Image 2 - Front yard of 16 Monaco Dr. and lower end of Oakville Lane.



Image 3 - View of runoff from new mall and resulting washout on Oakville Lane.



47 Monaco Drive - flooding in front yard.

45 Monaco Drive - flooding in front yard up to the front steps.

43 Monaco Drive - Flooding in front yard.

18 Monaco Drive - front yard, back yard and basement flooded.

19 Monaco Drive - flooded for the first time after the storm pipe was connected to the existing pipe on Monaco Drive, from the new Dental Office. Flooded in the back yard up to the foundation.

16 Monaco Drive - front yard, back yard and basement flooded. See Image 1 and 2.

9 Monaco Drive - front yard, back yard and basement flooded.

The source of the flooding at 43,45 and 47 Monaco Drive was from the ditch on the opposite side of Monaco Drive.

Location of water flowing from the new mall. See image 3.

**LEGEND**

HIGH WATER MARK H

DIRECTION OF PHOTOGRAPH #